


## Pt100 1/10 Class B

### Order nr.: 809650 1014

Pt100 measuring elements are the most widely used measuring elements in industrial temperature measurement technology. The reasons for this include their long-term stability, the large measuring range and their high measuring accuracy. According to IEC 751 / EN 806751, this Pt100 has accuracy class 1/10 B and a measuring range of 0 °C to +100 °C.



Technical data	
Sensor Type	Pt100
Accuracy	1/10 Class B according to IEC 751 / EN 60751 $dT = \pm(1/10 \cdot (0,30 \text{ °C} + 0,005 t ))$
Measuring range	$\pm 0 \text{ °C}$ to $+100 \text{ °C}$

Technical drawing	
	<p>A: 0,35            B: 2            C: 15            K: <math>6 \pm 1</math>            in mm</p>